



ONSITE CHECKLIST FOR TECHS - MOVE-IN DAY

CHECKLIST FOR EVERY VEHICLE - MOVE IN

- Be sure each vehicle is carrying an eighth (1/8th) of a tank of fuel or less.**
- Adjust eyelet terminal to match example**
- Hot door unlock and roll down windows (if windows have no decals/stickers)**
- Open moon/sunroof and open rear hatch/trunk lid**
- Hot lead battery cable must be disconnected from terminal**
 - Hot lead is Red/Negative, and Positive does not need to be disconnected from terminal**
- All loose cable ends taped. Any metal on terminal posts should be taped over. All exposed metal must be covered.**
- Vehicle battery connected to the DLS-90 converter (Connecting to the 12-V side of the battery)**
 - Red Negative lead from DLS-90 should be connected to Red Battery Terminal Lead (not the battery terminal)**
 - Black Positive (+) can have the black lead from DLS-90 connected directly to the positive battery terminal.**
- Place and tape rubber round over the positive side of the clamp on the battery.**
- Deliver the key to each vehicle to the Auto Expo Show Office located just in the lobby facing Elm St. just past ticket windows and main entrances to the Expo floor.**



CHECKLIST FOR EVERY VEHICLE - MOVE OUT

- Reconnect the hot lead battery cable to terminal**
- Remove tape from all loose cable ends**
- Disconnect vehicle from the DLS-90 converter and reconnect to vehicle battery**